





FATADA LATERALA STANGA



FATADA LATERALA DREAPTA



S.C. TOTALAIG ENVIRO SERV S.R.L. J40 / 5119 / 2012 Calea Dorobanti, nr. 111-135, bl. 9E, sc.C, et.2, ap.60, Sector 1, Bucuresti			Denumire: Reabilitare termica Bloc 1 Adresa: str. Florilor, nr. 1 Beneficiar: PRIMARIA SECTOR 1	PR.NR.:21/2014 J-AC/261-S FAZA: PT+DE
SPECIFICATIE Sef Proiect Proiectat Desenat	NUME ing. Dobra Ovidiu arh. Crina Barbulescu ing. Doroftei Mihai	SEM NATURA 	Scara: 1:100 Data: ianuarie 2016	Titlul plansei FATADA LATERALA STANGAT FATADA LATERALA DREAPTA existent PLANSA: NR.: A08