


situatia existenta scara: 1/100



situatie propusa scara: 1/100



- 1.poarta auto in doua foi existenta
- 2.soclu gard din beton armat
- 3.panou de gard din tabla profilata
- 4.stalpi din teava de otel $D=100\text{ mm}$
- 5.porti auto rulante propuse
- 6.poarta pietonala existenta



ORDINUL ARHITECTILOR
X. DIN ROMANIA
1730
Aprilian Mihai
PETRESCU
REFACERE PARTIA
Bd. Armatorilor
Benef: Stanescu

scara	VEDERE STRADA	A1
1/50		